



MOUNT VERNON FR

Wear it for life

Our recommended laundry instructions are as follows.

Home Laundering:

Wash on permanent press cycle with warm or hot water. Tumble dry on permanent press cycle. Remove garments when dry or slightly damp and place on hanger. Garments may be ironed for a smoother appearance.

Industrial Laundering:

We recommend normal IL cotton wash formulas. Water temperature should not exceed 165°F. Any recognized commercial laundry detergent that does not contain bleach is satisfactory. Stack temperature should not exceed 165°F for best appearance and lowest shrinkage.

Dry Cleaning:

Garments may be dry cleaned if needed and may be helpful in removing oily soils. Some dry cleaning fluids are flammable and must be completely removed from FR garments to maintain protective performance.

Materials to avoid:

Chlorine bleach (sodium hypochlorite) or oxygenated bleach (hydrogen peroxide) alone or in combination with other materials will harm the flame resistant properties and should never be used for FR garments.

FR garments should not be starched or processed with fabric softener. Starch and some fabric softeners may be flammable. Both starch and fabric softener have the potential to build up on fabric surfaces over multiple wash cycles and may reduce the protection of FR garments.

Please contact me if any additional information is needed,

Craig Tutterow
Mount Vernon Mills
FR Technical Director
706-734-4923

11.10.20